



### Spis elementów

C1, C5, C13, C14..	100µF/100V	4	R1, R3 .....	2,2K	1	R17 .....	1K	1	PRI... wieloobrotowy	4, 7K	1	D1, D4, D5, D2	zenera	15V/1W	4
C2 .....	MKT 2,2µF	1	R2, R9, R15 .....	10K/1W	3	R19, R20 .....	100 ohm/1W	2	T1, T2, T3, T4 .....	BC546B	4	D3, D6 .....	IN4007	2	
C3 .....	470pF	1	R4, R5 .....	100 ohm	2	R18 .....	82 ohm	1	T5, T9, T10 .....	MJE340	3	D7, D8 .....	IN5408	2	
C4 .....	100µF/50V	1	R6 .....	10K	1	R23, R24, R25, R26 .....	470 ohm	4	T6, T7 .....	MJE350	2	Złącze ....	konektor 6, 3mm	5	
C6 .....	220µF/25V	1	R7, R12 .....	470 ohm	2	R27, R28, R29, R30 .....	470 ohm	4	T8 .....	B139	1	Złącze .....	NS-25-2	1	
C7 .....	100µF/63V	1	R8, R22 .....	15K	2	R31, R32, R33, R34..	0,22 ohm/5W	4	T11, T12, T13, T14 ..	IRFP240	4	Złącze .....	Gniazdo bezpiecznika .....	2	
C8, C9 .....	10pF/500V	2	R10 .....	10K	1	R35, R36, R37, R38..	0,22 ohm/5W	4	T15, T16, T17, T18 ..	IRFP240	4	Bezpiecznik	8A .....	2	
C10 .....	10nF/100V	1	R11 .....	4,7 ohm/2W	1										
C11 .....	22pF/500V	1	R13, R21 ..	100 ohm/1W	2										
C12 .....	470µF/63V	1	R14 .....	120 ohm/1W	1										
C15 .....	100nF/250V	1	R16 .....	4,7K	1										